

PO Box 217 Leander, TX USA 78646-0217 • 800-621-9598 • sales@glemco.com • www.glemco.com

A Resource for Semiconductor Manufacturers



## **CDO Liner Assembly**



Item	P/N	Description	OEMs	Qty
1	45570	CDO Liner	423-57-003	1
Glemco offers	s improvemei	nts, modifications, or alternatives to standard OEM replacement con	nponents as indicated in red through	out this
	PO Box 21	7 Leander, TX USA 78646-0217 • 800-621-9598 • sales@g	lemco.com • www.glemco.com	
			G	30-047PH1



## Glemco Customized Design CDO Showerhead Assembly

45571

The standard OEM shower has a fixed shower head that provides an inefficient shower curtain inside the CDO. It's small tube can become clogged during use, which limits scrubber effectiveness. Also, it's welded design requires that the entire unit be replaced if it becomes clogged.

Glemco introduces an upgraded shower head assembly for the CDO Abatement System, that is designed to increase productivity and improve performance with these advancements...



Item	P/N	Description	OEMs
1	45571-1	Showerhead Body	No OEM Reference
2	45571-2	Spray, Cone	No OEM Reference
3	8B157	Fog Nozzle	No OEM Reference

\* Glemco offers improvements, modifications, or alternatives to standard OEM replacement components as indicated in red throughout this guide.

PO Box 217 Leander, TX USA 78646-0217 • 800-621-9598 • sales@glemco.com • www.glemco.com



## CDO Flange Assembly With Demisters



Item	P/N	Description	OEMs	Qty
1	45574S	CDO Flange Assembly	No OEM Reference	1
2	45575S	Lower Demister	No OEM Reference	1
3	45576S	Upper Demister	No OEM Reference	1

\* Glemco offers improvements, modifications, or alternatives to standard OEM replacement components as indicated in red throughout this guide.

PO Box 217 Leander, TX USA 78646-0217 • 800-621-9598 • sales@glemco.com • www.glemco.com